

Mercedes-Benz  
Currently Approved Phones



It's essential, use only Mercedes-Benz approved handsets and software levels:  
Mercedes-Benz hands-free systems are perhaps the most capable in-vehicle cellular systems available today. Whether you choose to use Bluetooth or a traditional cradle interface, each system is deeply integrated into your vehicle to provide the fullest range of functions. Only by using Mercedes-Benz approved handsets with approved software levels will you be guaranteed trouble-free performance and access to all supported functions.



Motorola V600  
GSM Unlocked  
Software: MB  
Proprietary



Motorola V3 RAZR  
AT&T / T-Mobile  
Software: 0E.42.09R,  
0E.42.0ER, 0E.40.57R,  
0E.41.C3R\_B,  
0E.C0.15R, 0E.42.15R



Motorola K1m  
Verizon  
Software:  
24.1\_00.25.0C



Motorola K1  
AT&T  
Software:  
R4527\_G\_08.42.0BR\_A



Motorola V3m  
Verizon  
Software:  
NEWC\_01.05.0A,  
NEWC\_01.09.02



Motorola V3i  
AT&T / T-Mobile  
Software:  
R47A\_G\_08.D9.3DR



Motorola Q  
Verizon  
Software:  
04.08.04P, 06.07.03P,  
06.0B.11P



Motorola E815  
Verizon  
Software:  
1.17.03, 01.1E.00



Motorola V710  
Verizon  
Software:  
MB Proprietary



Motorola L7 SLVR  
AT&T  
Software:  
R4517\_G\_08.C4.1ER,  
R4517\_G\_08.C4.25R



Motorola U6 PEBL  
T-Mobile  
Software:  
08.83.76R,  
08.83.76R\_A



Blackberry 8703e  
Verizon  
Software:  
4.1.0.344



Blackberry 8700g  
T-Mobile  
Software: 4.1.0.346

Blackberry 8700c  
AT&T  
Software: 4.1.0.377



Motorola V60s  
Verizon  
Software:  
MB Proprietary



Apple iPhone  
AT&T  
Software:  
1.0.1, 1.0.2, 1.1.1



LG Chocolate  
Verizon  
Software:  
T85VZ03



Blackberry 8830  
Verizon / Sprint  
Software: 4.2.2.66



Blackberry 8800  
AT&T  
Software: 4.2.1.72



Blackberry Curve 8300  
AT&T  
Software: 4.2.2.89,  
2.4.0.39



Motorola V557  
AT&T  
Software:  
08.28.3DR\_A3,  
08.28.40R



Nokia 6230  
AT&T / T-Mobile  
Software: 4.43,  
5.35, 5.50



Motorola V325i  
Verizon  
Software:  
MLNBT1\_01.07.00R



Motorola RAZR2 V9m  
Verizon  
Software:  
PARS\_01.15.0D



Motorola RAZR2 V9  
AT&T  
Software:  
U\_9C.13.37R\_1



Motorola Q9m  
Verizon  
Software:  
C\_03.20.0EP



Motorola RIZR Z3  
T-Mobile  
Software:  
R452B\_G\_08.01.02R



Nokia 5300  
T-Mobile  
Software: V05.02



Motorola 6133  
T-Mobile  
Software: V05.23



Blackberry 7250  
Verizon  
Software:  
4.0.0.204



Blackberry 7290  
Cingular /  
T-Mobile  
Software:  
4.0.2.32



Blackberry 8100g  
Cingular /  
T-Mobile  
Software:  
4.0.0.219



Kyocera Strobe  
K612B  
Alltel  
Software: SL1.0.00



LG VX8100  
Verizon  
Software:  
T81VZV05



LG VX9800  
Verizon  
Software:  
T98VZV01



Motorola V3c  
Verizon  
Software:  
GATW\_1.0F.03,  
GATW\_01.15.04



Motorola V3t  
T-Mobile  
Software:  
R3443U5\_G\_0E.C8.0DR

Alltel  
Software:  
GATW\_04.06.00R



Motorola ROKR E1  
AT&T  
Software:  
30.34R\_A



Motorola V551  
AT&T  
Software:  
8.18.16R\_OA



Motorola V3xx  
AT&T  
Software:  
R26111LD\_U\_96.  
71.95R



Blackberry 7100G  
Cingular /  
T-Mobile  
Software:  
4.0.0.219

Auto Wireless Solutions is an expert provider of phones, accessories and account services. That's why Mercedes-Benz chose Auto Wireless Solutions.

For assistance on getting the correct phone and service for your Mercedes-Benz, contact AWS by phone or online.

Auto Wireless Solutions  
800.910.1021  
[www.wireless4MB.com](http://www.wireless4MB.com)