



12/2009

Handset selection for use with V60 Bluetooth Cradle Adaptor

Handset Model	Carrier	Required Software Level	PN	Applicable Adaptor
Apple iPhone	AT+T	v1.1.4	Visit your local mobile phone center.	 
BlackBerry 8100	Cingular	v4.2.0.69		
BlackBerry 8830	Verizon /Sprint	V4.3.0.100		
Motorola V330	T-Mobile	08.18.1DR		
Motorola PEBL U6	T-Mobile	08.83.76R, 08.83.76R_A		
Motorola V551	Cingular	08.18.16R_OA		
Motorola V557	Cingular	08.28.3DR_A3, 08.28.40R		
Motorola SLVR L7	Cingular	08.C4.1ER, 08.C4.25R		
Motorola Q	Verizon	04.08.04P, 06.07.03P		
Motorola Q9m	Verizon	C_03.20.0EP		
Motorola K1m	Verizon	24.1_00.25.0C		
Motorola K1	Cingular	R4527_G_08.42.0BR_A		
Motorola RAZR V3	T-Mobile / Cingular	0E.42.09R, 0E.42.0ER,0E.40.57R, 0E.41.C3R_B, 0E.CO.15R, 0E.42.15R		
Motorola V3c	Verizon	01.0F.03, 01.15.04		
Motorola V3m	Verizon	NEWC_01.05.0A		
Motorola V3t	T-Mobile	R3443U5_G_0E.C8.0DR		
Motorola RAZR² V9m	Verizon	PARS_01.15.0D		
Motorola E815	Verizon	01.17.03, 01.1E.00		
Motorola Rokr Z6	Verizon	PARS_01.16.0C		
Nokia 6555	AT&T	V04.51	B67875855	
Nokia 5300	T-Mobile	V05.02		
Palm Centro	Sprint	CENTRO-1.00		
MBMotorola V710	Verizon	MB proprietary SW		
			BQ6820922	